

ePIPE® Stops Water Loss in London area Swimming Pool – Puts Owners Back into the Swim

Problem

With an estimated water loss of 3500 litres per day through leaking pipes, the cost of maintaining the pool was forcing the owner to shut it down during one of the hottest English summers on record. Even worse the traditional dig and fix option was uneconomical and would have resulted in the pool still being out of service well into the autumn.

Solution

Pipe Restoration Services were tasked with repairing the leaking pipes, in-place using ePIPE's patented technology.

Restoration steps included:

- 1) Pressure tests identified leaks on the skimmer and return pipes.
- 2) Isolation of the leaking pipes.
- 3) Drain, dry and prepare the pipe work for the ePIPE barrier /leak sealant coating.
- 4) Application of the barrier/leak sealant coating into each pipe section.
- 5) After a short curing process of 2 hours, a pressure test was applied.

Result: no loss of pressure, leaks sealed.

- 6) Return the pool to service

This project was completed in a 1½ days, no excavations required.

Customer comment: "Thanks to the guys at PRS I now have a pool to be proud of and enjoy.

The whole job was carried out without excavating which no one else could offer; they made life so easy we can now get back to enjoying the summer again.

Miracles do happen." - Mr. P. Huckle

For further information
www.piperestorationservices.co.uk

